



January 31, 2023.

Board of Directors
The Marina at the Bluffs Condominium Association, Inc.
1550 Marina Isle Way
Jupiter, FL 33477

■
1806 Old Okeechobee Road
Suite A
West Palm Beach, FL 33409
Ph: 561-581-8800
www.epicforensics.com

**Re: Milestone Inspection Report – Phase One.
Building 21.
2101 Marina Isle Way, Jupiter, FL 33477**

Dear Board of Directors,

At the request of **The Marina at the Bluffs Condominium Association, Inc.** (“Client”), **Epic Forensics & Engineering, Inc.** (“Epic”) performed a “Milestone Inspection” of the property located at **2101 Marina Isle Way, Jupiter, FL 33477** per the new 2022 Legislature Subsection 4-D. The areas observed by Epic included, the exterior elevations of the building, the roof, the common corridor areas, two stairs, all available and readily accessible private balcony units (30 out of 30), the exterior surroundings of the building (landscape areas) and front Porte Cochere and trash room. This on-site assessment was performed by Epic on April 22, 2022. The purpose of this milestone inspection was to perform a non-destructive, visual review of the current condition of the property. It is Epic’s opinion that a significant number of structural elements were observed sufficient to afford reasonable assurance that, in Epic’s professional opinion, such elements are representative of a significant portion of the exterior facades and available, readily accessible, and visible elements of the building framing system. Based on the 2022 legislature SB-4D, the milestone inspection is required for *“the purpose of attesting to the life safety and adequacy of the structural components of the building and, to the extent reasonably possible, determining the general structural condition of the building as it affects the safety of such building, including a determination of any necessary maintenance, repair, or replacement of any structural component of the building. The purpose of such inspection is not to determine if the condition of an existing building is in compliance with the Florida Building Code or the fire safety code”*.

Deficiencies noted within this report are limited to items that, if not properly addressed, could potentially pose a **future** risk to the life or safety of the occupants of the Buildings (including residents, guests, staff and pets), as well as conditions that could potentially contribute to and/or cause significant structural damage to the Buildings during **future** severe storm or wind events. Deficiencies described within this report are based on the limited scope of work described above and are not intended to represent an all-inclusive or exhaustive review of the Buildings in their

totality. The specific deficiencies described herein, as well as any other like-kind conditions encountered throughout the Buildings, should be addressed in a timely manner (as described in further detail below) in order to protect the occupants and maintain the intended structural integrity of the Building. To facilitate the Client's planning, repairs should be started within 90-days of the date of this report.

Under section 553.899, "***Mandatory structural inspections for condominium and cooperative buildings***". Subsection 4, The milestone inspection is required, and the building's initial milestone inspection must be performed before December 31, 2024.

As indicated in Section 553.899, Subsection 8(c), based on the Milestone Inspection Phase One, during the visual examination of habitable and non habitable areas of a building, including the major structural components of the building, Epic did not observe any "Substantial Structural Deterioration".

As defined in Section 553.899, subsection 2(b), "*Substantial structural deterioration*" means substantial structural distress that negatively affects a building's general structural condition and integrity. The term does not include surface imperfections such as cracks, distortion, sagging, deflections, misalignment, signs of leakage, or peeling of finishes unless the licensed engineer or architect performing the phase one or phase two inspection determines that such surface imperfections are a sign of substantial structural deterioration".

It is Epic's opinion that based on the current condition of the observed building components at the time of the assessment, the Property is deemed to be Structurally safe for continued use under the present occupancy with qualifications listed below. The deficiencies observed in the property shall be promptly addressed to prevent continuing deterioration. Currently, the observed deficiencies do not represent a significant or "substantial structural deterioration", but if not properly addressed and corrected within the timeframe noted above, they may negatively affect the general structural condition and integrity of the building. See "***Substantial Structural Deterioration***" items below.

As indicated above, the deficiencies observed at the property are not an immediate structural concern for the integrity of the building, however they may represent an unsafe condition to the building occupants. Deficiencies listed below are life-safety related and have been deemed "High Priority" repairs (i.e., potential threat to life-safety) and must be repaired/restored promptly. See "***Life-safety related***" items below.

Per Section 553.899, Subsection 8(e), items that are currently damaged but are not considered substantial structural deterioration shall be listed and recommended remedial or preventive repairs are proposed for the Association to address. See "***Non-Substantial Structural Deterioration***" items below.

BACKGROUND INFORMATION

The current subject property consists of twenty-two (22) 5-story buildings, containing a total of 660 residential units, and is located at Marina Isle Way, Jupiter, FL 33477. The buildings are numbered from 5 thru 26 and are located around the marina where repairs and renovations are currently being performed by a General Contractor hired by the Marina Association (see **Exhibit #1**, showing building numbers and associated street address numbers; management and dockmaster offices are also shown for reference). Shown below in red lettering is Building 21 (2101) associated with the deficiencies listed in this milestone inspection report.




Exhibit 1: Aerial photograph of the property with building numbers and address numbers. (Source: Google Maps 2020)

SUBSTANTIAL STRUCTURAL DETERIORATION

- It was observed at the balcony slab of unit 201 several superficial cracks parallel to the edge of the slab (long side). Also it appeared that the slab was deflecting when multiple people walked near the edge of the cantilevered portion. In a abundance of caution, the balcony was temporarily and remains shored to date (see **Photo #1**).



Photo #1. View of temporary post shores at balcony of unit 201.

- Additional investigation is required as part of the “Milestone Inspection” phase 2, which will be conducted at a later date (within the next 90 days). Epic has requested the Association to provide existing plans for the building to perform the necessary review and analysis of the existing field condition discussed above.

LIFE-SAFETY RELATED

- Balcony guardrail vertical posts with visible separation and/or gaps between the concrete wall of the concrete pocket and the post (see **Photo #2**). In several locations, a metal ruler was able to be inserted to depths of up to 2 inches. Moisture was observed at the end of the ruler upon removal from the gap. Also, moisture was observed ponding in low spots around the post base. This condition indicates moisture has penetrated the base of the post and could cause damage to the concrete and corrosion of the reinforcement in the slab. Further evidence of moisture within the railing post base can be observed at locations with vegetation and/or organic growth (See **Photo #3**). Also, at several locations, the degree of deterioration of the post base grout allows unwanted lateral movement of the guardrail system top member or top rail.



Photo #2. View of post base missing grout (unit 205 front corridor).



Photo #3. View of post base with vegetation growth (unit 304 front corridor).

Proposed remedial repairs:

Since the existing guardrail system is not “current” code compliant, the guardrail system cannot be removed or un-installed from the current location. If the guardrail is removed, a new current code compliant system shall be installed in its place. For that reason, we recommend the following remedial actions:

- At locations where concrete/grout cracks, delamination, and/or spalling is identified, remove all grout to expose the embedded portion of railing post and remove adjoining cracked, delaminated and/or spalled concrete.
- Remove all grout, corrosion, scale, slurry, and other bond-inhibiting material from exposed railing post by thorough wire-brushing or high-pressure water blasting.

- Install weep hole at post base above finishes.
- Replace removed concrete non-shrink non-metallic grout around the post.
- Prime railing posts to a minimum of 1-inch above the finish concrete surface to provide adequate grout-to-aluminum isolation.
- Seal around post base with sealant.
- Plaster finish and paint the repair area to match the surroundings.

NOTE: this is not a repair protocol to correct the observed deficiency. Detailed procedures and material specifications shall be prepared prior to correcting the issue(s) listed above. Repair protocols shall be properly submitted to the applicable building departments and building permits shall be obtained prior to commencement of work.

- Balcony floors and exterior edges with imminent concrete spalls. This condition can also be caused by insufficient rebar concrete coverage and by superficial cracks that allow moisture intrusion. Corrosion present at reinforcing steel produces expansion of the diameter of the bar which leads to displacement of surface materials, in this case, concrete (See **Photos #4 and #5**). Due to the uncertainty of this condition, it is not possible to predict if or when the finishes will fall. We recommend removing the deficient portions of the finishes or concrete elements from the slab edges or ceilings to prevent pieces of debris from falling down and hurting residents.




Photo #4. View of imminent spalling of concrete slab edge observed at floor of unit 301 balcony.




Photo #5. View of imminent spalling of concrete slab edge observed at edge of floor slab (Unit 402 balcony shown).

NON-SUBSTANTIAL STRUCTURAL DETERIORATION ITEMS

- Balcony ceiling and exterior edges with exposed and corroded reinforcement bars. This condition can be caused by insufficient rebar concrete coverage and by superficial cracks that allow moisture intrusion. Corrosion present at reinforcing steel produces expansion of the diameter of the bar (exfoliation) which leads to displacement (jacking) of surface finishes, such as stucco. This condition can be observed prior to stucco/concrete finishes failure, in the form of bulging of the exterior finishes and after finishes have been removed or displaced by the expansion of the reinforcing bar due to corrosion (see **Photos #6 and #7**).




Photo #6. View of deteriorated ceiling stucco finishes, signs of concrete slab spalling due to corroded reinforcing, condition observed at ceiling of unit 402 front corridor.




Photo #7. View of spalled concrete due to rebar corrosion (Unit 405 balcony shown).

- In certain instances, this condition can be concealed by finishes that have not yet failed or have been covered by previous repairs. This condition requires additional invasive evaluations to clearly define the limits of the deficiency.
- Exterior sealants around door and window observed with signs of deterioration (cohesion failure). This condition can allow wind driven rain to enter the building envelope and cause damage to the concrete elements as well as damage to interior finishes, personal property and create environmental contamination such as mold and mildew. Sealant shall be removed and replaced preferably with a paintable and UV resistant silicone or hybrid sealant material (See **Photo #8**).




Photo #8. View of deteriorated sealant around the front door of unit 402.

- Anchors for hurricane shutters observed with severe deterioration in the form of corrosion. This condition will compromise the structural integrity of the shutters under severe wind events. Expansion of the anchor due to severe corrosion will damage the concrete and can allow moisture to enter and damage reinforcing bars within the slab (see **Photo #9**). Corroded anchors shall be replaced with corrosion resistant anchors.




Photo #9. View of deteriorated metal anchors for the hurricane shutters. Observed at several units (Unit 506 shown).

- Balcony ceiling and exterior edges with exposed and corroded metals and corroded steel elements observed at numerous units. This condition refers to metals used in the slab during construction, and also metals installed after construction (see **Photo #10**). Exposed corroded metals shall be removed by grinding metals to a depth of at least 1 inch, coating remains of metal elements in cavity, patching hole and finish or paint to match existing adjacent areas.




Photo #10. Close up view of embedded metals within concrete slabs. (Unit 205 balcony shown).

- Also, it was observed, at private balcony units with floor finishes (i.e. tile) installed up to the edge of the slab and the edge of the tile perimeter completely sealed preventing water that enters through grout lines or cracks to escape. In many cases water accumulates with no way to drain out damaging the finishes and potentially the concrete and reinforcement within the slabs (See **Photo #11**).




Photo #11. View of floor finishes (tile) with edges sealed (Unit 503 balcony shown).

- The above discussed deficiencies are considered “***Non-substantial structural deterioration***”, deficiencies observed do not constitute a structural-related or life-safety related issue, however if they are not addressed in a timely manner (i.e. during the next 90 or the next scheduled building painting, (whichever timeline is less). With long-term exposure to the aggressive environmental conditions that exist at this property, these deficiencies can worsen and lead to damages to the structure. Epic recommends that “***Non-substantial structural deterioration***” items be monitored by the Association’s Staff minimum on a monthly basis and to alert Epic if any of those conditions worsens. Epic’s report can be used as the baseline for comparison and record keeping by the Association’s Staff.

Below at the end of the report is attached (***Appendix #1***) a list in table form (***Table #1***) of all the unit balconies accessed and balcony areas observed from adjacent locations. The table below shows the observed deficiencies noted during Epic’s inspections. Notes and photos shown above are representative examples of each deficiency observed in the building. Cells in the table below highlighted with red indicate that a photo of this deficiency is shown above. Conditions identified in the table below will look similar to the example photo shown above.



The Marina at the Bluffs Condominium Association, Inc.
Milestone Inspection Report – Phase One.
Building 21, 2101 Marina Isle Way, Jupiter, FL 33477
January 31, 2023
Page 11 of 13

This space intentionally left blank

CLOSURE

The opinions and recommendations expressed in this document are based on a review of the noted material, as well as my education, training, and experience as a licensed, professional engineer, and have been reached within a reasonable degree of engineering probability. These opinions and recommendations are based on the information currently available to me and may be amended or supplemented should new information become available.

As a routine matter, in order to avoid possible misunderstanding, nothing in this document should be construed directly or indirectly as a guarantee for any portion of the building/structure. To the best of my knowledge and ability, this document represents an accurate appraisal of the present condition of the building/structure based upon careful evaluation of observed conditions, to the extent reasonably possible.

This document has been prepared in accordance with the applicable professional standard of care. No other warranties or guarantees, expressed or implied, are made or intended. This document has been prepared solely for the Client or its authorized representatives for the purpose stated herein and should not be relied upon by any other party or for any other purpose. The conclusions in this letter are based on the limited investigation described above. Should additional information become available, Epic reserves the right to re-evaluate and/or supplement the opinions, comments, and/or recommendations provided herein, and to issue a revised version of, or supplement to, this letter, if deemed necessary.

Any reliance on this document by any party other than the Client shall be without liability to Epic or its employees.


Please contact Epic at 561-581-8800 if you have any questions.

Respectfully submitted,
EPIC FORENSICS & ENGINEERING, INC.
Registry 30519

*This item has been digitally signed and sealed by the
engineer named below on the date adjacent to the seal.
Printed copies of this document are not considered signed
and sealed, and the signature must be verified on any*

By:

Roberto Rotundo, P.E.
Florida License No. 88658



Digitally signed
by Roberto
Rotundo
Date: 2023.01.31
18:34:04 -05'00'

"As a routine matter, in order to avoid possible misunderstanding, nothing in this report should be construed directly or indirectly as a guarantee for any portion of the structure. To the best of our knowledge and ability, this report represents an accurate appraisal of the present condition of the building based upon careful evaluation of observed conditions, conditions, to the extent reasonably possible."



Appendix #1

Table #1 – Accessed Residential Balcony Unit List - Observed deficiencies.

Building		Deficiencies																					
		Railings					Stucco Deficiencies					Concrete			Others								
		Loose	Falling Paint	Gap Observed	Moisture evident	Bad Post Pockets	Cracks (LF)	Overhead (SF)	Walls (SF)	Slab (SF)	Edge (SF)	Cracked Slab (LF)	Exposed Rebar	Spalling Slab (SF)	Cracked Tile	Door sealant	Unsealed Electrical Box	Vegetation	Unsealed Anchors	Waterproofing deficient (SF)	Moisture Stains (SF)	Corroded anchors (Shutters)	Rust Spots
2101																							
	Units																						
Balconies (rear of building)	506																						
	505							2															
	504																						
	503							1		3													
	502																						
	501		1			1		2		2	2												
	406														1			1	1				1
	405											1											
	404									3													
	403																						
	402						2																
	401																	1					
	306					1					6												
	305					1				2													
	304																						
	303					3		2		6								1					
	302					1		4		2													
	301																	1					
	206					1	2			4													
	205		1							2													1
	204										2								2				
	203					1	4				2												
	202												4										
	201						2	2		4	1			6				1					
	106							5						2									
	105																						
	104							2															
	103																						
	102																						
101									10														
Corridors (front of building)	Units																						
	506					2						4		1								2	
	505				1	1						12								1			
	504				1	1		0.5				12								1			
	503				1	1		0.5				30											
	502			1				0.5				10											
	501					1		0.5															
	406					3		2		1					1								
	405															1							
	404					1						20		1									
	403					1						18							1				
	402					1			0.5				28										
	401					2							24		1								
	306												4									1	
	305								0.5														
	304												24										
	303												20				1						
	302												16							3			
	301												18										
	206																						
	205						1	0.5					4										
	204						1						28								2	1	
	203												30		1								
	202								3				26										
	201						1	0.5					24										
	106															1							
	105																						
	104																						
	103																						
102																							
101																							
Exterior	Location																						
	Front						0.5		1		47.5	0.5											
	Left										6												
	Right																						
	Rear										9.5												

Table #1 – Accessed Residential Balcony Unit List - Observed deficiencies.

Table #1 – Accessed Residential Balcony Unit List - Observed deficiencies.